MATERIAL SAFETY DATA SHEET This MSDS complies with OSHA'S Hazard Communication Standard 29 CFR 1910.1200 and OSHA Form 174

IDENTITY AND MANUFA					
	HMIS Rating: Health-1; Flammability-3; Reactivity-0; Personal Protection-B				
	DOT Hazard Classific				
	DOT Haz Classification(pretransition): Consumer Commodity ORM-D				
	dentity (trade name as used on label):				
Address: St. Joseph, MO 64501	Quick & Clean				
	Extreme Odor Neutralizer Handheld Part #HIL0113654				
	MSDS Number: A00266 AM Revision-first issue-a				
	Date Prepared: 09/24/09 Prepared By: IB				
NOTICE: JUDGEMENT BASED ON INDIRECT TEST DATA Information Calls: (770)422-2071 SECTION 1 - MATERIAL IDENTIFICATION AND INFORMATION					
		-		40000	0
COMPONENTS-CHEMICAL NAMES AND COMMON NAMES (Hazardous Components 1% or greater; Carcinogens 0.1% or greater)	CAS Number SARA OSHA PEL ACGIH Carcinogen III LIST (ppm) TLV (ppm) Ref. Source **				
ACETONE	67-64-1 No 1000 750 d				
ISOBUTANE / PROPANE BLEND	75-28-5	No	NE	NE	d
	74-98-6	No	1000	1000	d
SECTION 2 - PHYSICAL/CHEMICAL CHARACTERISTICS					
oiling Point: N/A Specific Gravity (H2O=1): Concentrate Only = < 1					
	Vapor Pressure (Non-Aerosols)(mm Hg and Temperature): N/A				
	Evaporation Rate (= 1): N/E				
	Water Reactive: No				
Appearance and Odor: Clear liquid with fragrance.					
SECTION 3 - FIRE AND EXPLOSION HAZARD DATA					
FLAMMABILITY as per USA FLAME PROJECTION TEST (aerosols): flar		mperature		lity Limits in A	Air by % in
projection with spray through cap: projection greater than 18" with flashba	ck: N/E		Volume:	– 0/	
	% LEL: N/E % UEL: N/E				
FLASH POINT AND METHOD USED (non-aerosols): N/A SPECIAL FIRE FIGHTING PROCEDURES: Provide shielding for personnel. Wear self-contained breathing apparatus. Cool containers with					
EXTINGUISHER MEDIA: Foam, dry chemical, carbon dioxide, water. water fog to prevent rupturing & spewing.					
Unusual Fire & Explosion Hazards: Do not expose aerosols to temperatures above 120°F or the container may rupture.					
SECTION 4 - REACTIVITY HAZARD DATA					
STABILITY [X] STABLE [] UNSTABLE HAZARDOUS POLYMERIZATION [] WILL [X] WILL NOT OCCUR					
Incompatibility (Mat. to avoid): Alkalis, oxidizing materials, amines. Conditions to Avoid: Open flame, welding arcs, heat.					
Hazardous Decomposition Products: CO, CO2.					
SECTION 5 - HEALTH HAZARD DATA					
PRIMARY ROUTES OF ENTRY: [X] INHALATION [] INGESTION [] SKIN ABSORPTION [] EYE [] NOT HAZARDOUS					
ACUTE EFFECTS Vapor concentrations around 1000 ppm may cause slight transient irritation to the upper respiratory tract.					
Inhalation: Excessive inhalation of vapors can be harmful and may cause headache, dizziness, asphyxia, anesthetic effects and possible					
unconsciousness.					
Eye Contact: Irritation. Skin Contact: May cause slight irritation.					
Ingestion: Possible chemical pneumonitis if aspirated into lungs. Nausea.					
CHRONIC EFFECTS: (Effects due to excessive exposure to the raw materials of this mixture) May cause mucous membrane irritation, overnight					
headache, and general weakness.					
Medical Conditions Generally Aggravated by Exposure: May aggravate existing eye, skin, or upper respiratory conditions.					
EMERGENCY FIRST AID PROCEDURES					
Eye Contact: Flush with water for 15 minutes. If irritated, seek medical attention.					
Skin Contact: Wash with soap and water. If irritated, seek medical attention.					
Inhalation: Remove to fresh air. Resuscitate if necessary. Get medical attention.					
Ingestion: DO NOT INDUCE VOMITING. Drink two large glasses of water. Get immediate medical attention.					
SECTION 6 - CONTROL AND PROTECTIVE MEASURES Respiratory Protection (specify type): If vapor concentration exceeds TLV, use respirator approved by U.S. Bureau of Mines / NIOSH for organic					
vapor.					
Protective Gloves: Latex, if skin easily irritated.	Eye Protection: Safet	y glasses	recommend	ed.	
Ventilation Requirements: Adequate ventilation to keep vapor concentration below TLV.					
Other Protective Clothing & Equipment: None					
Hygienic Work Practices: Wash with soap and water before handling food. Remove contaminated clothing.					
SECTION 7 - PRECAUTIONS FOR SAFE HANDLING AND USE					
Steps To Be Taken If Material Is Spilled Or Released: Absorb with suitable medium. Incinerate or landfill according to local, state or federal regulations. DO NOT FLUSH TO SEWER.					
Waste Disposal Methods: Aerosol cans when vented to atmospheric pressure through normal use, pose no disposal hazard.					
Precautions To Be Taken In Handling & Storage: Do not puncture or incinerate containers. Do not store at temperatures above 120°F. Other Precautions &/or Special Hazards: KEEP OUT OF REACH OF CHILDREN. Avoid food contamination. Avoid breathing vapors. Remove					
ignition sources. We believe the statements, technical information and recommendations contained herein are reliable, but they are given without warranty or guarantee of any kind.					
We believe the statements, technical information and recommendations contain	d harain ara raliahla hut t	hav ara aiv	on without wa	rranty or quar	antoo of any kind

** Chemical Listed as Carcinogen or Potential Carcinogen. [a] NTP [b] IARC Monograph [c] OSHA [d] Not Listed [e] Animal Data Only