MATERIAL SAFETY DATA SHEET

This MSDS complies with OSHA'S Hazard Communication Standard 29 CFR 1910.1200 and OSHA Form 174

IDENTITY AND MANUI	FAC	TURER'S INFORMA	TION				
NFPA Rating: Health-1; Flammability-3; Reactivity-0; Special	HMIS Rating: Health-1; Flammability-3; Reactivity-0; Personal Protection-B						
Manufactured For: Hillyard Industries, Inc.	DO.	DOT Hazard Classification (post transition): LIMITED QUANTITY					
Address: 302 N. 4 th Street	DO.	DOT Haz Classification(pretransition): Consumer Commodity ORM-D					
Address: St. Joseph, MO 64501	lder	Identity (trade name as used on label):					
	VANILLA AIR FRESHENER						
	Part# HIL0104554						
Phone: (816)-233-1321 ext. 8285 or http://www.hillyard.com	MSDS Number: A00207 Revision-4a						
EMERGENCY RESPONSE NUMBER: Chemtrec 1-800-424-9300	Date Prepared: 02/01/07 Prepared by: IB						
NOTICE: JUDGEMENT BASED ON INDIRECT TEST DATA Information Calls: (770)422-2071							
SECTION 1 - MATERIAL IDE	NTII	FICATION AND INFO	ORMATI	ON			
COMPONENTS-CHEMICAL NAMES AND COMMON NAMES		CAS Number	SARA	OSHA PEL	ACGIH	Carcinogen	
(Hazardous Components 1% or greater; Carcinogens 0.1% or greater)			III LIST	(ppm)	TLV (ppm)	Ref. Source **	
ACETONE		67-64-1	No	1000	750	d	
ISOBUTANE / PROPANE BLEND		75-28-5	No	800	800	d	
		74-98-6	No	1000	1000	d	
SECTION 2 - PHYSICAL/CHEMICAL CHARACTERISTICS							
Boiling Point: N/A	Specific Gravity (H2O=1): Concentrate Only = 0.8						
Vapor Pressure: PSIG @ 70°F (Aerosols): 50-60	Vapor Pressure (Non-Aerosols)(mm Hg and Temperature): N/A						
Vapor Density (Air = 1): N/E	Evaporation Rate (= 1): N/E						
Solubility in Water: Soluble	Wat	er Reactive: No					
Appearance and Odor: Clear liquid with fragrance.		DI 00101111474DD	- · - ·				
SECTION 3 - FIRE AND) EXI			I			
FLAMMABILITY as per USA FLAME PROJECTION TEST (aerosols):							
flame projection with spray through cap: projection greater than 18" with	h	h N/E % LEL: N/E % UEL: N/E				% UEL: N/E	
flashback: Categorized as EXTREMELY FLAMMABLE							
FLASH POINT AND METHOD USED (non-aerosols): N/A SPECIAL FIRE FIGHTING PROCEDURES: Provide shielding for personnel. Wear self- contained breathing apparatus. Cool containers with water fog to prevent rupturing & spewing.							
Unusual Fire & Explosion Hazards: Do not expose aerosols to temperatures above 120°F or the container may rupture.							
SECTION 4 - REACTIVITY HAZARD DATA							
STABILITY [X] STABLE [] UNSTABLE HAZARDOUS POLYMERIZATION [] WILL [X] WILL NOT OCCUR							
Incompatibility (Mat. to avoid): Alkalis, oxidizing materials, amines. Conditions to Avoid: Open flame, welding arcs, heat.							
Hazardous Decomposition Products: CO, CO2.							
SECTION 5 - HEALTH HAZARD DATA							
PRIMARY ROUTES OF ENTRY: [X]INHALATION []INGESTION []SKIN ABSORPTION []EYE []NOT HAZARDOUS							
ACUTE EFFECTS Vapor concentrations around 1000 ppm may cause slight transient irritation to the upper respiratory tract.							
Inhalation: Excessive inhalation of vapors can be harmful and may cause headache, dizziness, asphyxia, anesthetic effects and possible							
unconsciousness.							
Eye Contact: Irritation.	Skin Contact: May cause slight irritation.						
,							
Ingestion: Possible chemical pneumonitis if aspirated into lungs. Nausea. CHRONIC EFFECTS: (Effects due to excessive exposure to the raw materials of this mixture) May cause mucous membrane irritation, overnight							
headache, and general weakness.							
Medical Conditions Generally Aggravated by Exposure: May aggravate existing eye, skin, or upper respiratory conditions.							
EMERGENCY FIRST AID PROCEDURES							
Eye Contact: Flush with water for 15 minutes. If irritated, seek medica							
Skin Contact: Wash with soap and water. If irritated, seek medical attention.							
Inhalation: Remove to fresh air. Resuscitate if necessary. Get medical attention.							
Ingestion: DO NOT INDUCE VOMITING. Drink two large glasses of water. Get immediate medical attention.							
SECTION 6 - CONTROL AND PROTECTIVE MEASURES							
Respiratory Protection (specify type): If vapor concentration exceeds TLV, use respirator approved by NIOSH or U.S. Bureau of Mines for organic vapor.							
Protective Gloves: Latex, if skin easily irritated. Eye Protection: Safety glasses recommended.							
Ventilation Requirements: Adequate ventilation to keep vapor concentration below TLV.							
Other Protective Clothing & Equipment: None							
Hygienic Work Practices: Wash with soap and water before handling food. Remove contaminated clothing.							
SECTION 7 - PRECAUTIONS FOR SAFE HANDLING AND USE Steps To Be Taken If Material Is Spilled Or Released: Absorb with suitable medium. Incinerate or landfill according to local, state or federal regulations. DO NOT							
FLÜSH TO SEWER.					or rederal reg	julations. DO NOT	
Waste Disposal Methods: Aerosol cans when vented to atmospheric pressure to					0005		
Precautions To Be Taken In Handling & Storage: Do not puncture or incinerate containers. Do not store at temperatures above 120°F. Other Precautions & for Special Hazards: KEEP OUT OF REACH OF CHILDREN, Avoid food contamination. Avoid breathing vapors, Remove ignition sources.							
TODAL FREGUNDOS MOT SPECIAL BAZAROS' MEET OUT OF REACH OF CHILD	~ - N	AVOID TOOD CONTAMINATI	OU AVOID	DIESHUNG VAN	us Remove I	CHURCH SOUTCAS	

her Precautions &/or Special Hazards: KEEP OUT OF REACH OF CHILDREN. Avoid food contamination. Avoid breathing vapors. Remove ignition sources.

We believe the statements, technical information and recommendations contained herein are reliable, but they are given without warranty or guarantee of any kind.

** Chemical Listed as Carcinogen or Potential Carcinogen. [a] NTP [b] IARC Monograph [c] OSHA [d] Not Listed [e] Animal Data Only