

MATERIAL SAFETY DATA SHEET

SNUGGLE FABRIC SOFTNER SHEETS Product Name Emergency (800)831-9889 I 95034 UPC-A 770128950340 SCC 10770128950347 Medical(Collect) (303)592-1024 Product Code Chemical Product Chemtree (800)424-9300 Manufacturer JOHNSONDIVERSEY INC. and Company 3630 E. KEMPER RD 03/20/2000 Date Indentification **CINCINNATI, OH 45241-2046 FABRIC SOFTNER** Chemical Family Chemical Name of Hazardous Ingredient Units **Exposure Limits** NONE Π Composition/ Information on Ingredients IRRITATING TO SKIN AND EYES. MISTS ARE IRRITATING TO SKIN, EYES AND RESPIRATORY TRACT. Signs U and Symptoms SAME AS ACUTE EFFECTS. Exposure Ш O Haz ards Identific ation HMIS: Health 1 Personal Protection Flammability 0 Reactivity В SENSITIVE SKIN. Conditions Aggravated Carcinogen Info NONE NTP **IARC OSHA** Target Organs or System Routes of Exposure: Inhalation Skin X Ingestion X X Inhalation REMOVE TO FRESH AIR AND SEEK MEDICAL ATTENTION. IV Eyes IMMEDIATELY FLUSH EYES WITH PLENTY OF WATER FOR 15 MINUTES. GET MEDICAL ATTENTION. First Aid Measures Skin FLUSH SKIN WITH PLENTY OF WATER. REMOVE AND LAUNDER CONTAMINATED CLOTHING BEFORE REUSE. GET MEDICAL ATTENTION FOR IRRITATION OR INJURY. Ingestion DO NOT INDUCE VOMITING. GET MEDICAL ATTENTION. NOTE: NEVER GIVE ANYTHING BY MOUTH T AN UNCONSCIOUS PERSON. WEAR FULL PROTECTIVE GEAR AND POSITIVE PRESSURE BREATHING Fire Control Measures/ APPARATUS (SCBA) IN FIRE AREA. Equipment V Flammable Property Info **NONE** Fire Fighting NONE KNOWN. **Explosion Info** Measures Extinguishing Media WATER, WATER SPRAY, CO2, FOAM OR DRY POWDER. NONE Gases

Printed: 02/06/2004

VI Accidental Measures	Spill and Leak Clean UP Procedures FLUSH SMALL AMOUNTS TO DRAIN. COLLECT AND RETURN LARGE AMOUNTS TO CONTAINER. THIS PRODUCT DOES NOT CONTAIN A REPORTABLE QUANTITY (RQ) UNDER CERCLA.
	Environmental Precautions
VII Handling and Storage	Ventilation Required? NONE Instructions NOT USUALLY REQUIRED.
	Safe Storage, Handling and Use Instructions STORE AT AMBIENT ROOM TEMPERATURE. AVOID CONTACT WITH HEAT OR MOISTURE.
	Imcompatible Materials STRONG OXIDIZING AGENTS.
	Protective Gloves IMPERMEABLE.
VIII	Eye Protection FACE SHIELD OR GOGGLES.
Exposure Controls/ Personal Protection	Respiratory NOT NORMALLY REQUIRED. Protection
	Other Protective WEAR CHEMICAL APRON WHEN NECESSARY. Clothing Equipment
IX Physical and Chemical Properties	Characteristics o of Hazardous Chemcial
	Vapor Pressure N/A MmHg@ NA °C Vapor Density(Air=1 N/A pH 4-6 Water Solubility 100 %
	Appearance & Odor BLUE VISCOUS OPAQUE FLORAL SHEET
	Boiling Point 212 °F Melting Point °F Flammability Limits in Air By Volume: Upper Lower Flash Point °F Auto Ignition °F Oxidizing Properties
	Specific Gravity .9895 Volatile by Volume N/A %
	Evaporation Rate(n-Butyl Acetate=1)
v	Peroxide, Pyrophoric, Unstable or Water Reactive STABLE
	Reactivity and Hazardous Polymerization NONE KNOWN.
X	Possible Hazardous Reactions NONE Conditions to Avoid NONE
Stability and Reactivity	Materials STRONG OXIDIZING AGENTS. To Avoid
	Hazardous OXIDES OF CARBON. Decomposition Products
XI Toxicological Information	
XII Ecological Information	Possible Effects and Environmental Fate NO DATA AVAILABLE.
	Degradability
	Aquatic Toxicity Method of USE UNTIL LESS THAN 1 INCH REMAINS IN CONTAINER, EMPTY CONTAINER
XIII Disposal Consideration	Method of Disposal, Residues and Safe Handling USE UNTIL LESS THAN 1 INCH REMAINS IN CONTAINER, EMPTY CONTAINER TRIPLE RINSE WITH WATER, ADD TO OPERATION. REMOVE OR DEFACE LABEL BEFORE SELLING CONTAINER OR DISPOSAL. DISPOSE IN A MANNER CONSISTENT WITH LOCAL, STATE, AND FEDERAL REGULATIONS.
	Disposal of OXIDES OF CARBON. Contaminated Material
XIV	SOFTENERS, FABRIC, N.O.I.
Transport Information	
XV-Regulatory Information XVI-Other Information	
S.A.R.A. Title III Section 313	NONE
State Right to Know Information	WATER - CAS #7732-18-5 FRAGRANCE - PROPRIETARY PRESERVATIVE - CAS #26172-55-4 & 2682-20-4 BLUE DYE - CAS #4474-24-2 DIHYDROGENATED TALLOW DIMETHYL CHLORIDE - CAS #61789-80-8